

Property Information

Property Names

Name Explanation	Name
Function/Location	Farmhouse, 10291 Old Ridge Road (Route 738)
Current	Fairview

Property Evaluation Status

Property Addresses

Current - 10291 Old Ridge Road Route 738

County/Independent City(s): Hanover (County)

Incorporated Town(s): *No Data*

Zip Code(s): 23005

Magisterial District(s): *No Data*

Tax Parcel(s): 7882-41-7025

USGS Quad(s): ASHLAND

Additional Property Information

Architecture Setting: Village

Acreage: *No Data*

Site Description:

2005: The house sits on high ground surrounded by large trees. The outbuildings are located some distance away. There are several large trees around the house and are located some distance from the house. A concrete sidewalk leads to the front of the dwelling. There are a corn crib and two stables associated with this dwelling.

Surveyor Assessment:

2005: This is a good example of a late-19th, early-20th century farm in Hanover County.

Surveyor Recommendation: Recommended for Further Survey

Ownership

Ownership Category	Ownership Entity
Private	<i>No Data</i>

Primary Resource Information

Resource Category: Domestic

Resource Type: Single Dwelling

NR Resource Type: Building

Date of Construction: ca 1900

Date Source: Site Visit

Historic Time Period: Reconstruction and Growth (1866 - 1916)

Historic Context(s): Architecture/Community Planning, Domestic

Other ID Number: *No Data*

Architectural Style: No Discernable Style

Form: *No Data*

Number of Stories: 2.0

Condition: Good

Interior Plan: Central Passage, Single Pile

Threats to Resource: Development

Cultural Affiliations: *No Data*

Cultural Affiliation Details: *No Data*

Architectural Description:

2005: This is a two-story, three-bay, frame dwelling sheathed in weatherboard. The wood windows are 2/2, double-hung sash. The one-story, one-bay porch has Tuscan columns. There are two, exterior-end brick chimneys. The gable roof has a central peak and is covered with standing-seam metal.

There is a two-story, frame ell on the rear of the dwelling with a porch on one side. "IDD 1908" is incised on the rear ell chimney.

Exterior Components

Component	Component Type	Material	Material Treatment
Roof	Gable	Metal	Standing Seam
Chimneys	Exterior End	Brick	No Data
Windows	Sash, Double-Hung	Wood	2/2
Structural System and Exterior Treatment	Frame	Wood	Weatherboard
Porch	1-story, 1-bay	Wood	Columns, Tuscan

Secondary Resource Information

Secondary Resource #1

Resource Category: Agriculture/Subsistence
Resource Type: Stable
NR Resource Type: Building
Date of Construction: ca 1930
Date Source: Site Visit
Historic Time Period: World War I to World War II (1917 - 1945)
Historic Context(s): Subsistence/Agriculture
Other ID Number: No Data
Architectural Style: No Discernable Style
Form: No Data
Number of Stories: 1.0
Condition: Good
Threats to Resource: Development
Cultural Affiliations: No Data
Cultural Affiliation Details: No Data
Architectural Description:

2005: This is a one-story, frame stables sheathed in plywood and metal siding.

Secondary Resource #2

Resource Category: Agriculture/Subsistence
Resource Type: Stable
NR Resource Type: Building
Date of Construction: ca 1930
Date Source: Site Visit
Historic Time Period: World War I to World War II (1917 - 1945)
Historic Context(s): Subsistence/Agriculture
Other ID Number: No Data
Architectural Style: No Discernable Style
Form: No Data
Number of Stories: 1.0
Condition: Good
Threats to Resource: Development
Cultural Affiliations: No Data
Cultural Affiliation Details: No Data
Architectural Description:

2005: This is a one-story, frame stable sheathed in metal siding.

Secondary Resource #3

Resource Category: Agriculture/Subsistence

Resource Type: Corncrib
NR Resource Type: Structure
Date of Construction: ca 1900
Date Source: Site Visit
Historic Time Period: Reconstruction and Growth (1866 - 1916)
Historic Context(s): Subsistence/Agriculture
Other ID Number: *No Data*
Architectural Style: No Discernable Style
Form: *No Data*
Number of Stories: *No Data*
Condition: Good
Threats to Resource: Development
Cultural Affiliations: *No Data*
Cultural Affiliation Details: *No Data*
Architectural Description:

2005: This is a one-story, frame corncrib sheathed in metal siding. The gable roof is covered with standing-seam metal.

Historic District Information

Historic District Name: *No Data*
Local Historic District Name: *No Data*
Historic District Significance: *No Data*

CRM Events

Event Type: Survey:Phase I/Reconnaissance

Project Review File Number: *No Data*
Investigator: Ashley M. Neville
Organization/Company: Ashley Neville LLC
Photographic Media: Film
Survey Date: 8/1/2005
Dhr Library Report Number: *No Data*
Project Staff/Notes:
No Data

Bibliographic Information

Bibliography:
No Data
Property Notes:
No Data